

Photo No.: 1	Date: 1/25/2017		Time: 14:45
Photographer:			Direction: East
Description: Location of the release.			



Photo No.: 2	Date: 1/25/2017	Time: 14:46
Photographer:		Direction: East
Description: Location of the release.		





Photo No.: 3	Date: 1/25/2017		Time: 14:47	
Photographer:			Direction: East	
Description: Trees show spray line of the release.				



Photo No.: 4	Date: 1/25/2017	Time: 14:51
Photographer:		Direction: East
Description: Culvert location. Culvert runs under driveway then surfaces on the other side.		





Photo No.: 5	Date: 1/25/2017		Time: 14:52
Photographer:			Direction: South
Description: Clearing location for staging.			



Photo No.: 6	Date: 1/25/2017	Time: 14:54
Photographer:		Direction: North
Description: Removing released product.		





Photo No.: 7	Date: 1/25/2017	Time: 14:55
Photographer:		Direction: East
Description: Release sprayed over road into field. Yellow snow is the spray area.		



Photo No.: 8	Date: 1/25/2017	Time: 16:29
Photographer:		Direction: South
Description: Willow creek downstream from release.		





